

Changelog for firmware 1096 v3.00

Supported hardware

This firmware only supports the following reader variants:

- Micro Card Reader (10115-xxx-xx and 10117-xxx-xx)
- Micro2 Card Reader (12115-xxx-xx and 12117-xxx-xx)

For older products, we recommend firmware 1096 v2.40.03.

Changelog

3.00.04 (2025-04-07)

Bug fixes

- Improved keyboard emulation compatibility to support additional MFP models [FW-754](#)

3.00.03 (2023-03-23)

Features

- The HID Prox number format *CardNumberLeftAdjusted* has been added.
For more details, refer to the [HidProxSerialNrFormat](#) configuration value. [FW-515](#)

Bug fixes

- Micro2 Card Reader (12115-xxx-xx and 12117-xxx-xx) failed to read HITAG 1/2/S, EM4205, and Cotag cards after approximately 7,000 readings. [FW-518](#)
- On Micro2 Card Reader (12115-xxx-xx and 12117-xxx-xx), multiple and incorrect readings of HITAG cards could occur. [FW-520](#)